

Louisville Metro Air Pollution Control District
Excess Emission Reports
5/9/2006 Through 6/11/2006

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 5/19/2006 at 05:54 AM Stopped: 5/19/2006 at 06:03 AM Report ID: **06911**

Problem Description: Pollutant: PART. OPACITY Equipment: Bag house

Opacity spike caused by bad bag in baghouse.

Reported: 5/19/2006 at 06:36 AM STATUS: WORKING

Started: 5/20/2006 at 05:42 PM Stopped: 5/20/2006 at 09:00 PM Report ID: **06912**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Damaged bgs in baghouse.

Reported: 5/20/2006 at : AM STATUS: WORKING

Started: 5/30/2006 at 05:15 PM Stopped: 5/30/2006 at 05:50 PM Report ID: **06918**

Problem Description: Pollutant: ODOR Equipment: C1T Column

Blown rupture disc.

Reported: 5/30/2006 at 06:22 PM STATUS: WORKING

3 Problems reported by plant 0011

Plant: 0214 Chevron USA, Bells Ln, 4410 Bells Ln

Started: 6/7/2006 at 09:00 AM Stopped: 6/7/2006 at 05:00 PM Report ID: **06922**

Problem Description: Pollutant: PART. OPACITY Equipment: Vapor recovery unit

The vapor recovery unit at the Lou Chevron Terminal will be down periodically between 0900-1700 today for preventive maintenance.

Reported: 6/7/2006 at 08:45 AM STATUS: WORKING

1 Problem reported by plant 0214

Plant: 0739 Dean Milk Company, 4420 Bishop Ln

Started: 5/25/2006 at 07:15 AM Stopped: at : AM Report ID: **06915**

Problem Description: Pollutant: ODOR Equipment: EQ Tank

Hole in top of tank due to rust allowing odor to escape.

Reported: 5/25/2006 at 11:19 AM STATUS: WORKING

1 Problem reported by plant 0739

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 5/25/2006 at 09:35 PM Stopped: 5/25/2006 at 10:05 PM Report ID: **06916**

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Reason unknown.

Reported: 5/25/2006 at 09:47 PM STATUS: WORKING

1 Problem reported by plant 0028

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 6/8/2006 at 02:10 PM Stopped: 6/9/2006 at 01:00 AM Report ID: 06923

Problem Description: Pollutant: PART. OPACITY Equipment: TA duct

The kiln was shutdown at 10:07 am due to blockage of material in the tursiary air duct.

Reported: 6/8/2006 at 02:10 PM STATUS: WORKING

1 Problem reported by plant 0060

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Started: 5/21/2006 at 01:01 PM Stopped: 5/21/2006 at 05:00 PM Report ID: 06913

Problem Description: Pollutant: SO2 Equipment: Sampling Equipment

Sampling equipment. I/E made repairs to sampling equipment.

Reported: 5/21/2006 at 03:10 PM STATUS: WORKING

Started: 6/5/2006 at 10:00 PM Stopped: 6/5/2006 at 11:00 PM Report ID: 06921

Problem Description: Pollutant: SO2 Equipment: Unknown

Maintaining higher SO2 setpoint to ease spillage on reaction tanks & soda ash screw feeder wasn't putting out much in AUTO.

Reported: 6/5/2006 at 10:00 PM STATUS: WORKING

2 Problems reported by plant 0126

Plant: 0149 Metro Sewer Dist,Morris Forman, 4522 Algonquin Pkwy

Started: 5/31/2006 at 02:23 PM Stopped: 5/31/2006 at 03:23 PM Report ID: 06919

Problem Description: Pollutant: ODOR Equipment: PTO fume Incin. #2

Fume incinerator low temperature alarm rec'd @ 14:23. Restarted but failed again @ 15:23. Back on line @ 16:00.

Reported: 5/31/2006 at 04:38 PM STATUS: WORKING

1 Problem reported by plant 0149

Plant: 0532 Outer Loop Recycling & Disp, 2673 Outer Loop

Started: 5/25/2006 at 10:15 AM Stopped: 5/25/2006 at 12:30 PM Report ID: 06917

Problem Description: Pollutant: PART. OPACITY Equipment: Flare -1

The main flare sump watered in, because of pump failure. 5-25-06, 10:15 hrs to 12:30 hrs. Flame arrester clogged up due to moisture and sludge. 5-25-06, 14:00 hrs to 17:15 hrs.

Reported: at : AM STATUS: WORKING

1 Problem reported by plant 0532

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 5/12/2006 at 09:30 PM Stopped: 5/13/2006 at 03:00 AM Report ID: 06910

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler 6

Boiler #6 start up. Line out boiler and bring up to temperature.

Reported: 5/12/2006 at 09:25 PM STATUS: WORKING

1 Problem reported by plant 1333

Plant: 0189 Rohm and Haas Company, 4300 Camp Ground Rd

Plant: 0189 Rohm and Haas Company, 4300 Camp Ground Rd

Started: 5/31/2006 at 07:53 AM Stopped: 5/31/2006 at 08:00 AM Report ID: 06920

Problem Description: Pollutant: PART. OPACITY Equipment: Dryer E-KV2-03-330

Flow aid material was being added to dryer when dryer doors opened. Material continued to be fed for 7 minutes.

When emptying system for maintenance, dryer doors opened prematurely.

Reported: 5/31/2006 at 02:50 PM

STATUS: WORKING

1 Problem reported by plant 0189
