

Louisville Metro Air Pollution Control District

Excess Emission Reports

1/10/2006 Through 2/7/2006

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 1/18/2006 at 05:30 PM Stopped: 1/18/2006 at 07:15 PM Report ID: **06852**

Problem Description: Pollutant: SO2 Equipment: Spray Reactor

Spray reactor drive unit failed.
Coal boilers were backed down and gas use was increased.

Reported: 1/18/2006 at 07:30 PM STATUS: WORKING

Started: 1/20/2006 at 04:36 PM Stopped: 1/20/2006 at 04:42 PM Report ID: **06853**

Problem Description: Pollutant: PART. OPACITY Equipment: #1 Baghouse

Bag or clamp off in #1 baghouse causing increased opacity.
Baghouses were isolated to determine which had failed.

Reported: 1/20/2006 at 05:30 PM STATUS: WORKING

Started: 1/24/2006 at 08:20 AM Stopped: 1/24/2006 at 05:15 PM Report ID: **06856**

Problem Description: Pollutant: SO2 Equipment: Coal Boilers

Maintenance. Possible SO2 emission.
SO2 emission never exceeded limit, spray reactor returned to service.

Reported: 1/24/2006 at 08:25 AM STATUS: WORKING

3 Problems reported by plant 0011

Plant: 0028 Borden Chemical, Inc, 6200 Camp Ground Rd

Started: 1/13/2006 at 06:00 PM Stopped: 1/14/2006 at 11:30 AM Report ID: **06850**

Problem Description: Pollutant: PART. OPACITY Equipment: Gas Boiler

Rec'd fax; maintenance, 1-13-06 @ 0600.
Rec'd ltr; re: equipment shutdown/start up, event dates: 1/13/06 & 1/14/06.

Reported: 1/13/2006 at 05:42 AM STATUS: WORKING

Started: 1/13/2006 at 05:00 AM Stopped: 1/13/2006 at 07:30 AM Report ID: **06849**

Problem Description: Pollutant: PART. OPACITY Equipment: Gas Boiler

Rec'd ltr. on 1/12/06, dated 1/10/06, re: equipment shutdown, event 1/13/06. Completion, 1/13/06 @ 7:30.

Reported: 1/13/2006 at 05:42 AM STATUS: WORKING

Started: 1/14/2006 at 07:30 AM Stopped: 1/14/2006 at 11:30 AM Report ID: **06851**

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

Rec'd fax; starting plant, 1/14/06 @ 0730.

Reported: 1/14/2006 at 11:36 AM STATUS: WORKING

Started: 1/21/2006 at 02:00 PM Stopped: 1/24/2006 at 10:30 PM Report ID: **06855**

Problem Description: Pollutant: PART. OPACITY Equipment: Silver FOrmaldehyde

Rec'd ltr; dated, 1-18-06, re: equipment shutdown, event 1/21/06 through 1/24/06.
Rec'd follow up notification ltr; dated 1-23-06, no bypass of silver plant boiler.

Reported: 1/21/2006 at : AM STATUS: WORKING

Plant: 0028 Borden Chemical, Inc, 6200 Camp Ground Rd

Started: 1/25/2006 at 11:00 AM Stopped: 1/26/2006 at 07:30 PM Report ID: **06857**

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

Shutdown equipment trouble, 11:00.
Rec'd ltr, dated 1-25-06, re: completion time.

Reported: 1/25/2006 at 11:00 AM STATUS: WORKING

Started: 1/26/2006 at 12:30 PM Stopped: 1/26/2006 at 04:00 PM Report ID: **06858**

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

Start up.

Reported: 1/26/2006 at 01:41 PM STATUS: WORKING

Started: 2/1/2006 at 05:15 PM Stopped: 2/6/2006 at 09:30 PM Report ID: **06859**

Problem Description: Pollutant: PART. OPACITY Equipment: Catalyst

Catalyst change.

Reported: 1/31/2006 at : AM STATUS: WORKING

7 Problems reported by plant 0028

Plant: 0650 Gene Snyder Building, 600 W Broadway

Started: 1/10/2006 at 09:30 AM Stopped: at : AM Report ID: **06860**

Problem Description: Pollutant: PART. OPACITY Equipment: Boilers

Will be testing operation of boilers on back up fuel supply. (#2 diesel fuel). Test should be complete within 2 hours of start time listed below.

Reported: 1/10/2006 at 08:50 AM STATUS: WORKING

1 Problem reported by plant 0650

Plant: 0115 Swift & Company, 1200 Story Ave

Started: 1/23/2006 at 07:30 AM Stopped: 1/23/2006 at 11:00 AM Report ID: **06854**

Problem Description: Pollutant: ODOR Equipment: Vapor Scrubber

Bleach pump was not putting enough bleach into scrubber sump. We have a temporary air pump in its place for now.

Reported: 1/23/2006 at 09:48 AM STATUS: WORKING

1 Problem reported by plant 0115
