

Louisville Metro Air Pollution Control District

Excess Emission Reports

May 2008

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 5/12/2008 at 04:10 PM Stopped: 5/12/2008 at 04:16 PM Report ID: **07462**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse issues

Baghouse issues.

Reported: 5/12/2008 at 04:10 PM STATUS: WORKING

Started: 5/20/2008 at 07:33 PM Stopped: at : AM Report ID: **07467**

Problem Description: Pollutant: PART. OPACITY Equipment: Fire/Explosion

Notified by Mike Reagan of American Synthetic Rubber of a small fire in there synthetic rubber plant during processing. No injuries or evacuations reported. There was no release to any out of plant environmental resources.

Reported: 5/20/2008 at 07:33 PM STATUS: WORKING

2 Problems reported by plant 0011

Plant: 0016 Anderson Wood Products, 1381 Beech St

Started: 5/30/2008 at 07:00 AM Stopped: at : AM Report ID: **07472**

Problem Description: Pollutant: PART. OPACITY Equipment: Kilns

Due to collapse of our large kilns we are having trouble generating steam for the small kilns without the boiler

smoking some. It is not continous and always white smoke. We are continually monitoring this problem and adjusting for this. Once the boiler reaches set point it throttles feed back and smokes when pressure drops and throttle comes back up.

Reported: 5/30/2008 at 10:10 AM STATUS: WORKING

1 Problem reported by plant 0016

Plant: 0026 Blue Grass Coop., Brown-Forman, 402 MacLean Ave

Started: 5/5/2008 at 03:15 PM Stopped: 5/8/2008 at 08:00 AM Report ID: **07459**

Problem Description: Pollutant: PART. DUST Equipment: Sawdust handling

Sawdust storage tank is releasing visible dust(dust not being captured by the air pollution control divice). Reason for malfunction is unknown at this time. Contractor has been contacted to evaluate the situation.

Reported: 5/5/2008 at 03:15 PM STATUS: WORKING

Started: 5/22/2008 at 10:00 AM Stopped: 5/26/2008 at 06:00 PM Report ID: **07469**

Problem Description: Pollutant: PART. OPACITY Equipment: Wood fired Boiler

Reference 07464 Startup of wood fired boiler.

Reported: 5/22/2008 at 10:00 AM STATUS: WORKING

Started: 5/22/2008 at 10:00 PM Stopped: at : AM Report ID: **07464**

Problem Description: Pollutant: PART. OPACITY Equipment: Wood Fired Boiler

Planned Shutdown.

Reported: 5/22/2008 at 10:00 PM STATUS: WORKING

3 Problems reported by plant 0026

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 5/13/2008 at 03:00 PM Stopped: 5/14/2008 at 06:00 PM Report ID: 07461

Problem Description: Pollutant: PART. OPACITY Equipment: maintenance

Shutdown for maintenance.

Reported: 5/13/2008 at 03:00 PM STATUS: WORKING

Started: 5/14/2008 at 10:40 PM Stopped: 5/14/2008 at 12:40 PM Report ID: 07463

Problem Description: Pollutant: PART. OPACITY Equipment: Stack Gas Boiler

Starting plant up.

Reported: 5/14/2008 at 10:40 PM STATUS: WORKING

2 Problems reported by plant 0028

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Started: 5/12/2008 at 08:00 AM Stopped: 5/12/2008 at 10:00 AM Report ID: 07460

Problem Description: Pollutant: PART. OPACITY Equipment: SDRS

Received by e-mail. Equipment involved SDRS.

Reported: 5/12/2008 at 08:00 AM STATUS: WORKING

1 Problem reported by plant 0126

Plant: 0127 Lou. Gas & Elec., Mill Creek, 14660 Dixie Hwy

Started: 5/19/2008 at 09:35 AM Stopped: 5/19/2008 at 09:49 AM Report ID: 07465

Problem Description: Pollutant: PART. OPACITY Equipment: Conveyor

Screw conveyor gasket leak releasing flyash.

Reported: 5/19/2008 at 09:35 AM STATUS: WORKING

1 Problem reported by plant 0127

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 5/21/2008 at 03:00 AM Stopped: 5/21/2008 at 11:30 AM Report ID: 07466

Problem Description: Pollutant: PART. DUST Equipment: Dryer

Dryer shutdown and cyclone cleaned.

Reported: 5/21/2008 at 03:00 AM STATUS: WORKING

1 Problem reported by plant 1333

Plant: 0189 Rohm and Haas Company, 4300 Camp Ground Rd

Started: 5/29/2008 at 04:10 PM Stopped: 5/29/2008 at 04:11 PM Report ID: 07471

Problem Description: Pollutant: PART. OPACITY Equipment: I Reactor KV3R-17-60

Over pressure of process vessel.

Reported: 5/29/2008 at 04:10 PM STATUS: WORKING

1 Problem reported by plant 0189

Plant: 0355 Waste Management of Kentucky, 7501 Grade Ln

Plant: 0355 Waste Management of Kentucky, 7501 Grade Ln

Started: 5/27/2008 at 09:00 AM Stopped: 5/27/2008 at 02:00 PM Report ID: **07468**

Problem Description: Pollutant: PART. OPACITY Equipment: Flare 1 & 2

Flare 1 will be shutdown automatically on Tuesday 5-27-08 to install new piping joints. Start up should be about 5 hours later about 14:00PM on 5-27-2008. Flare 2 will be started before flare 1 is shutdown to maintain negative pressure on the field.

Reported: 5/27/2008 at 09:00 AM

STATUS: WORKING

1 Problem reported by plant 0355

Plant: 1264 Zeochem, 1314 S 12 St

Started: 5/29/2008 at 01:00 PM Stopped: 5/29/2008 at 01:30 PM Report ID: **07470**

Problem Description: Pollutant: PART. OPACITY Equipment: Powder Storage

During transfer of powder from the ring dryer to the powder storage silo a flex line burst discharging approximately 100 pounds of powder to the atmosphere. Since it was on the roof we didn't notice until alerted by the neighbors. We shut down process immediately.

Reported: 5/29/2008 at 01:00 PM

STATUS: WORKING

1 Problem reported by plant 1264
