

Louisville Metro Air Pollution Control District
Excess Emission Event Reports
November 2008

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 11/3/2008 at 07:04 AM Stopped: at : AM Report ID: **07548**

Problem Description: Pollutant: PART. OPACITY Equipment: Overflow

Taulene leak.

Reported: 11/3/2008 at 07:04 AM STATUS: WORKING

Started: 11/15/2008 at 05:00 PM Stopped: 11/15/2008 at 05:07 PM Report ID: **07549**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Baghouse issues.

Reported: 11/15/2008 at 05:00 PM STATUS: WORKING

Started: 11/26/2008 at 02:00 PM Stopped: 11/26/2008 at 05:00 PM Report ID: **07555**

Problem Description: Pollutant: PART. OPACITY Equipment: Spray Reactor

Spray reactor disk.

Reported: 11/26/2008 at 02:00 PM STATUS: WORKING

3 Problems reported by plant 0011

Plant: 0016 Anderson Wood Products, 1381 Beech St

Started: 11/26/2008 at 01:00 PM Stopped: 11/26/2008 at 05:30 PM Report ID: **07556**

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

Due to equipment failure the boiler was down from 11:45am until 4:10PM. After repairing equipment when I restarted the boiler it smoked for about 2-3 minutes. I turned it off and reset parameters relative to correct speeds. After repairing equipment (smoked only from about 4:10PM till 4:13PM.

Reported: 11/26/2008 at 01:00 PM STATUS: WORKING

1 Problem reported by plant 0016

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 11/25/2008 at 12:15 AM Stopped: 11/30/2008 at 08:00 AM Report ID: **07550**

Problem Description: Pollutant: PART. OPACITY Equipment: Shutdown

Notice of planned shutdown and startup 11-25-2008 thru 11-30-2008.

Reported: 11/25/2008 at 12:15 AM STATUS: WORKING

1 Problem reported by plant 0028

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 11/23/2008 at 01:01 PM Stopped: 11/23/2008 at 01:09 PM Report ID: **07553**

Problem Description: Pollutant: PART. OPACITY Equipment: Pump

At 12:57 hours, the 526 In line Raw Mill suddenly shut down due to a failure on a pump. The shut down resulted in loss of power to the fan on the mill's baghouse on 13:01 hours. Fugitive dust exited the 526 Mill Building and went northeast along the railroad track running through the property. At 13:09 hours, the 545 baghouse was back on line. At 13:19 hours the 526 in line raw mill was back on line.

Reported: 11/24/2008 at 01:01 PM STATUS: WORKING

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

1 Problem reported by plant 0060

Plant: 0189 Rohm and Haas Company, 4300 Camp Ground Rd

Started: 11/19/2008 at 09:05 PM Stopped: 11/20/2008 at 12:15 AM Report ID: 07551

Problem Description: Pollutant: PART. OPACITY Equipment: Flange

Leaking Flange.

Reported: 11/19/2008 at 09:05 PM STATUS: WORKING

1 Problem reported by plant 0189

Plant: 0115 Swift & Company, 1200 Story Ave

Started: 11/26/2008 at 11:00 AM Stopped: 11/26/2008 at 01:30 PM Report ID: 07554

Problem Description: Pollutant: PART. OPACITY Equipment: Upper Scrubber

New bleach pump failed on upper scrubber at 11:15am. Put back up pump on-line 11:30am.

Reported: 11/26/2008 at 11:00 AM STATUS: WORKING

1 Problem reported by plant 0115

Plant: 0355 Waste Management of Kentucky, 7501 Grade Ln

Started: 11/19/2008 at 08:00 AM Stopped: 11/19/2008 at 06:30 PM Report ID: 07552

Problem Description: Pollutant: PART. OPACITY Equipment: Blower Failure

Blower failure is in review, but believe it was cause by regulating valve for Toro Energy, closing when they shut down. Their valve closed when it was to open. They were checkin the valve.

Reported: 11/19/2008 at 08:00 AM STATUS: WORKING

1 Problem reported by plant 0355
