

Louisville Metro Air Pollution Control District
Excess Emission Reports
April 2008

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 4/1/2008 at 05:06 AM Stopped: 4/1/2008 at 05:12 AM Report ID: **07445**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse issues

Baghouse issues.

Reported: 4/1/2008 at 05:06 AM STATUS: WORKING

Started: 4/2/2008 at 04:10 PM Stopped: 4/9/2008 at 10:00 AM Report ID: **07447**

Problem Description: Pollutant: PART. OPACITY Equipment: Spray Reactor

Conditions have arisen that necessitate a change out of the spray reactor disc and gearbox. This will help to ensure a reliable backup in the event of a disc drive failure. The spray reactor maintenance will occur on April 4, 2008.

Reported: 4/2/2008 at 04:10 PM STATUS: WORKING

2 Problems reported by plant 0011

Plant: 0026 Blue Grass Coop., Brown-Forman, 402 MacLean Ave

Started: 4/10/2008 at 10:00 AM Stopped: 4/10/2008 at 11:30 AM Report ID: **07453**

Problem Description: Pollutant: PART. OPACITY Equipment: sawdust handling

Sawdust handling system Unit U5B shutdown.

Reported: 4/10/2008 at 10:00 AM STATUS: WORKING

Started: 4/22/2008 at 12:15 PM Stopped: 4/22/2008 at 01:30 PM Report ID: **07458**

Problem Description: Pollutant: PART. OPACITY Equipment: Wood fire boiler

Wood Fired Boiler Unit U5a.

Reported: 4/22/2008 at 12:15 PM STATUS: WORKING

2 Problems reported by plant 0026

Plant: 0047 CONCO, Inc., 4000 Oaklawn Dr

Started: 4/9/2008 at 06:53 AM Stopped: 4/9/2008 at 07:20 AM Report ID: **07448**

Problem Description: Pollutant: PART. OPACITY Equipment: Spill

Cromic Acid spill. Acid did get into the sewer system and MSD is on the scene.

Reported: 4/9/2008 at 06:53 AM STATUS: WORKING

1 Problem reported by plant 0047

Plant: 0739 Dean Milk Company, 4420 Bishop Ln

Started: 4/17/2008 at 12:00 PM Stopped: 4/17/2008 at 02:00 PM Report ID: **07455**

Problem Description: Pollutant: PART. OPACITY Equipment: Pump Failure

At approximately 12:00PM Thursday April 17th we had a chemical pump failure. This pump injects chlorine into the air scrubber to assist with odor removed. We received a visit from Samuel Bate from APCD to inform us of a complaint. The pump was changed and system was back in normal operation at 2:00PM.

Reported: 4/18/2008 at 08:30 AM STATUS: WORKING

Plant: 0739 Dean Milk Company, 4420 Bishop Ln

1 Problem reported by plant 0739

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 4/4/2008 at 06:20 AM Stopped: 4/4/2008 at 08:20 AM Report ID: 07452

Problem Description: Pollutant: PART. OPACITY Equipment: Stack gas boiler

Olant shut down.

Reported: 4/4/2008 at 06:20 AM STATUS: WORKING

Started: 4/4/2008 at 05:35 AM Stopped: 4/4/2008 at 08:20 AM Report ID: 07450

Problem Description: Pollutant: PART. OPACITY Equipment: silver formaldehyde

Shutdown and startup.

Reported: 4/4/2008 at 05:35 AM STATUS: WORKING

Started: 4/8/2008 at 01:00 PM Stopped: at : AM Report ID: 07449

Problem Description: Pollutant: PART. OPACITY Equipment: Maintenance

Maintenance shutdown.

Reported: 4/8/2008 at 01:00 PM STATUS: WORKING

Started: 4/11/2008 at 11:45 PM Stopped: 4/12/2008 at 02:30 AM Report ID: 07457

Problem Description: Pollutant: PART. OPACITY Equipment: Gas stack boiler

Plant start up.

Reported: 4/11/2008 at 11:45 PM STATUS: WORKING

Started: 4/11/2008 at 07:15 AM Stopped: 4/11/2008 at 09:15 AM Report ID: 07454

Problem Description: Pollutant: PART. OPACITY Equipment: Gas Boiler

Gas Boiler went out.

Reported: 4/11/2008 at 09:41 AM STATUS: WORKING

5 Problems reported by plant 0028

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 4/19/2008 at 07:20 PM Stopped: 4/19/2008 at 10:30 PM Report ID: 07456

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler #6

Boiler startup #6

Reported: 4/19/2008 at 07:20 PM STATUS: WORKING

1 Problem reported by plant 1333