

Louisville Metro Air Pollution Control District

Excess Emission Reports

7/11/2006 Through 8/2/2006

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 7/14/2006 at 07:30 PM Stopped: 7/14/2006 at 07:54 PM Report ID: 06951

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Heavy rain downpour.

Reported: 7/14/2006 at : AM STATUS: WORKING

Started: 7/21/2006 at 06:24 PM Stopped: 7/21/2006 at 06:42 PM Report ID: 06959

Problem Description: Pollutant: PART. OPACITY Equipment: SDR

Heavy rain-system went out. Back in no other indicators of malfunction. All systems responding properly- no visual emissions.

Reported: 7/21/2006 at 06:52 PM STATUS: WORKING

2 Problems reported by plant 0011

Plant: 0026 Blue Grass Coop., Brown-Forman, 402 McLean Ave

Started: 7/25/2006 at 11:30 PM Stopped: at : AM Report ID: 06961

Problem Description: Pollutant: PART. OPACITY Equipment: C-8 Process Cyclone

Received fax on 7/29/06 at 2:01 pm. Shutting down C-8 process cyclone for 26.5 hours. Daily visible emission readings will be taken.

Reported: 7/29/2006 at 02:01 PM STATUS: WORKING

Started: 7/25/2006 at 09:00 AM Stopped: 7/25/2006 at 09:15 AM Report ID: 06960

Problem Description: Pollutant: PART. OPACITY Equipment: C-8, process cyclon

C-8, process cyclone.

Reported: 7/25/2006 at 08:56 AM STATUS: WORKING

2 Problems reported by plant 0026

Plant: 0001 Carbide Industries LLC, 4400 Bells Ln

Started: 7/31/2006 at 11:15 PM Stopped: 8/1/2006 at 03:00 AM Report ID: 06962

Problem Description: Pollutant: ODOR Equipment: Flange

Employees discovered a leaking flange. Employees contained the spill and stopped the leak within 30 minutes. Approximately 500 gallons of hydrochloric acid was captured in the secondary containment dike. Lime was used to neutralize the acid.

Reported: 8/1/2006 at 01:00 PM STATUS: WORKING

1 Problem reported by plant 0001

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 7/11/2006 at 12:30 AM Stopped: 7/11/2006 at 04:30 AM Report ID: 06946

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Unit start up.

Rec'd ltr; re: equipment startup/shutdown, dated, 7-11-06.

Reported: 7/11/2006 at : AM STATUS: WORKING

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 7/11/2006 at 08:15 PM Stopped: 7/11/2006 at 08:30 PM Report ID: 06949

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Reason unknown.
Ltr rec'd, event date: 7-11-06

Reported: 7/11/2006 at : AM STATUS: WORKING

Started: 7/11/2006 at 10:45 AM Stopped: 7/11/2006 at 11:28 AM Report ID: 06945

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Equipment failure.
Equipment shutdown/start up notification letter, event date 7/11/06.

Reported: 7/11/2006 at : AM STATUS: WORKING

Started: 7/14/2006 at 02:00 PM Stopped: 7/14/2006 at 07:15 PM Report ID: 06952

Problem Description: Pollutant: PART. OPACITY Equipment: Blower

Blower failure.

Reported: at : AM STATUS: WORKING

Started: 7/14/2006 at 02:45 PM Stopped: at : AM Report ID: 06953

Problem Description: Pollutant: PART. OPACITY Equipment: unknown

Bad Q2 meter on UR boiler.

Reported: at : AM STATUS: WORKING

Started: 7/15/2006 at 09:45 PM Stopped: 7/15/2006 at 12:00 AM Report ID: 06955

Problem Description: Pollutant: PART. OPACITY Equipment: Unit

Unit start up.

Reported: at : AM STATUS: WORKING

Started: 7/15/2006 at 05:00 PM Stopped: at : AM Report ID: 06954

Problem Description: Pollutant: PART. OPACITY Equipment: Blower

Heat over load, blower shut down.

Reported: at : AM STATUS: WORKING

Started: 7/16/2006 at 10:25 AM Stopped: 7/16/2006 at 12:25 PM Report ID: 06957

Problem Description: Pollutant: PART. OPACITY Equipment: unknown

Unit start up.

Reported: at : AM STATUS: WORKING

Started: 7/16/2006 at 04:00 AM Stopped: at : AM Report ID: 06956

Problem Description: Pollutant: PART. OPACITY Equipment: Catalyst

Unit shut down. Problem with catalyst.

Reported: at : AM STATUS: WORKING

9 Problems reported by plant 0028

Plant: 0019 Kent Feeds, Inc., 932 E Chestnut St

Started: 7/17/2006 at 07:00 AM Stopped: 7/18/2006 at 01:00 PM Report ID: 06958

Problem Description: Pollutant: PART. OPACITY Equipment: Thermo oxidizer

The block plant is scheduled to be in full production for the next four days.
Notice of shutdown. There will not be any more block production for today.

Reported: at : AM STATUS: WORKING

Plant: 0019 Kent Feeds, Inc., 932 E Chestnut St

1 Problem reported by plant 0019

Plant: 0149 Metro Sewer Dist, Morris Forman, 4522 Algonquin Pkwy

Started: 7/31/2006 at 03:00 PM Stopped: at : AM Report ID: **06963**

Problem Description: Pollutant: ODOR Equipment: #1 sedimentation tank

We are required to take #1 sedimentation tank in the Primary area (1 of 4 totals) for maintenance. Upon draining the tank the solids residue in the bottom became septic due to high ambient temperatures. This generated odors detectable off plant site. Draining should be completed by Wed., 8/2 and restored (cleaned) by our contractor API. We will advise.

Reported: 8/1/2006 at 03:00 PM STATUS: WORKING

1 Problem reported by plant 0149

Plant: 0115 Swift & Company, 1200 Story Ave

Started: 7/13/2006 at 07:00 AM Stopped: 7/14/2006 at 11:55 AM Report ID: **06950**

Problem Description: Pollutant: PART. OPACITY Equipment: Scrubber

Caustic pump not working, will call when repairs are made.

Repairs made, per phone call to Tim Priddy's voice mail @ 11:55 a.m. on 7/14/06.

Reported: 7/13/2006 at 07:15 AM STATUS: WORKING

Started: 8/2/2006 at 10:00 AM Stopped: at : AM Report ID: **06964**

Problem Description: Pollutant: ODOR Equipment: Upper scrubber

Had to replace bleach pump.

Reported: 8/2/2006 at 11:20 AM STATUS: WORKING

2 Problems reported by plant 0115
