

Louisville Metro Air Pollution Control District
Excess Emission Reports
November 2007

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 11/3/2007 at 04:40 AM Stopped: 11/3/2007 at 04:40 AM Report ID: **07337**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Baghouse release 6 minutes of opacity.

Reported: 11/3/2007 at 04:40 AM STATUS: WORKING

Started: 11/5/2007 at 12:08 AM Stopped: 11/5/2007 at 12:08 AM Report ID: **07336**

Problem Description: Pollutant: PART. OPACITY Equipment: container

Tolyerlene spill, however this has been contained.

Reported: 11/5/2007 at 12:08 AM STATUS: WORKING

Started: 11/9/2007 at 01:20 PM Stopped: 11/9/2007 at 01:34 PM Report ID: **07338**

Problem Description: Pollutant: PART. OPACITY Equipment: Coal Boilers

Notice of low lime solids from the Coal boilers.

Received follow up notification 11/09/2007

Reported: 11/9/2007 at 01:20 PM STATUS: WORKING

Started: 11/15/2007 at 10:30 AM Stopped: 11/15/2007 at 11:10 AM Report ID: **07343**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Baghouse shutdown #10

Reported: 11/15/2007 at 10:30 AM STATUS: WORKING

Started: 11/23/2007 at 09:42 AM Stopped: 11/23/2007 at 09:48 AM Report ID: **07348**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

6 minute excess emissions.

Reported: 11/23/2007 at 09:42 AM STATUS: WORKING

Started: 11/23/2007 at 01:36 PM Stopped: 11/23/2007 at 01:42 PM Report ID: **07349**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

6 minute excess emissions.

Reported: 11/23/2007 at 01:36 PM STATUS: WORKING

Started: 11/25/2007 at 02:24 PM Stopped: 11/25/2007 at 02:30 PM Report ID: **07350**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

6 minute excess emissions.

Reported: 11/25/2007 at 02:24 PM STATUS: WORKING

Started: 11/26/2007 at 05:06 PM Stopped: 11/26/2007 at 05:12 PM Report ID: **07351**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

SO2 out on 6 minute average. Isolated bad baghouse.

Reported: 11/26/2007 at 05:06 PM STATUS: WORKING

8 Problems reported by plant 0011

Plant: 0026 Blue Grass Coop., Brown-Forman, 402 MacLean Ave

Plant: 0026 Blue Grass Coop., Brown-Forman, 402 MacLean Ave

Started: 11/3/2007 at 06:00 AM Stopped: 11/3/2007 at 04:10 PM Report ID: 07335

Problem Description: Pollutant: PART. OPACITY Equipment: Wood fire Boiler

Wood Fire Boiler Unit 5A. Shutdown required for maintenance on the boiler feed chute.

Reported: 11/3/2007 at 06:00 AM STATUS: WORKING

Started: 11/20/2007 at 10:30 AM Stopped: 11/24/2007 at : AM Report ID: 07344

Problem Description: Pollutant: PART. OPACITY Equipment: Wood Fired Boiler

Planned shutdown for Thanksgiving Holiday.

Reported: 11/20/2007 at 10:30 AM STATUS: WORKING

Started: 11/20/2007 at 10:30 PM Stopped: 11/25/2007 at 05:15 PM Report ID: 07347

Problem Description: Pollutant: PART. OPACITY Equipment: Wood Fired Boiler

Wood Fire Boiler Unit 5 Startup and Shutdown notice.

Reported: 11/20/2007 at 10:30 PM STATUS: WORKING

3 Problems reported by plant 0026

Plant: 0001 Carbide Industries LLC, 4400 Bells Ln

Started: 11/13/2007 at 04:40 PM Stopped: 11/13/2007 at 04:53 PM Report ID: 07342

Problem Description: Pollutant: PART. OPACITY Equipment: Furnace Cooling Syst

Leak in the furnace cooling system required the water to be temporarily turned off to make repairs. Furnace was shutdown the water line closed resulting in smoke emitting from the emergency unit.

Reported: 11/13/2007 at 04:54 PM STATUS: WORKING

1 Problem reported by plant 0001

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 11/20/2007 at 09:00 PM Stopped: 11/21/2007 at 02:00 AM Report ID: 07352

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

Tube Leak of the LRU Boiler. Approximately less than 1 lb of phenol was released from the LRU and PF-2 process area.

Reported: 11/20/2007 at 09:00 PM STATUS: WORKING

Started: 11/27/2007 at 10:20 AM Stopped: 11/27/2007 at 12:05 PM Report ID: 07353

Problem Description: Pollutant: PART. OPACITY Equipment: Plant Start up

Plant start up.

Reported: 11/27/2007 at 10:20 AM STATUS: WORKING

2 Problems reported by plant 0028

Plant: 0620 John Conti Coffee, 4023 Bardstown Rd

Started: 11/13/2007 at 08:45 AM Stopped: 11/13/2007 at 01:00 PM Report ID: 07340

Problem Description: Pollutant: PART. OPACITY Equipment: After burner

Mark Nethery called their after burner is offline today to replace a gas valve.

Reported: 11/13/2007 at 08:45 AM STATUS: WORKING

1 Problem reported by plant 0620

Plant: 0019 Kent Feeds, Inc., 932 E Chestnut St

Plant: 0019 Kent Feeds, Inc., 932 E Chestnut St

Started: 11/28/2007 at 08:00 PM Stopped: at : AM Report ID: 07354

Problem Description: Pollutant: ODOR Equipment: motor

Blower motor on the after burner. Shutting down production until repairs are completed.

Reported: 11/28/2007 at 08:00 PM STATUS: WORKING

1 Problem reported by plant 0019

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 11/21/2007 at 02:30 AM Stopped: 11/21/2007 at 04:00 AM Report ID: 07346

Problem Description: Pollutant: PART. DUST Equipment: Preheat Tower

Blockage on 651 airslide dust occurred intermittently during this time. Processors and maintenance unblocked airslide and cut back tons per hour of feed on the kiln.

Reported: 11/21/2007 at 02:30 AM STATUS: WORKING

Started: 11/21/2007 at 08:00 AM Stopped: 11/21/2007 at 08:40 AM Report ID: 07345

Problem Description: Pollutant: PART. DUST Equipment: Transfer Line

Transfer line on top of cement silo is leaking, maintenance is working on the issue to correct the leak

Reported: 11/21/2007 at 08:00 AM STATUS: WORKING

2 Problems reported by plant 0060

Plant: 0148 Lou Med Center Steam Plant, 235 Abraham Flexner Way

Started: 11/29/2007 at 09:30 AM Stopped: 11/29/2007 at 10:25 AM Report ID: 07355

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Demand increase causing swing load opacity. Bag house off due to bag change yesterday. Baghouse back on line in 30 minutes should correct. 10:25AM Company called back and they have given an all clear.

Reported: 11/29/2007 at 09:30 AM STATUS: WORKING

1 Problem reported by plant 0148

Plant: 0149 Metro Sewer Dist, Morris Forman, 4522 Algonquin Pkwy

Started: 11/13/2007 at 11:00 PM Stopped: at : AM Report ID: 07341

Problem Description: Pollutant: PART. OPACITY Equipment: Primary Tank

#Operator error an instrument to measure sludge blanket levels was dropped into the #1 primary tank jamming the mechanism and requiring emergency shutdown.

Reported: 11/13/2007 at 01:00 PM STATUS: WORKING

1 Problem reported by plant 0149
