

Louisville Metro Air Pollution Control District
Excess Emission Event Reports
March 2009

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 3/14/2009 at 04:00 PM Stopped: 3/14/2009 at 06:00 PM Report ID: **07615**

Problem Description: Pollutant: PART. OPACITY Equipment: Spray Reactor

Spray reactor drive failure.

Reported: 3/14/2009 at 04:00 PM STATUS: WORKING

Started: 3/25/2009 at 12:30 PM Stopped: 3/25/2009 at 01:00 PM Report ID: **07618**

Problem Description: Pollutant: PART. OPACITY Equipment: Steam Boiler

Loss and recovery of steam boiler caused process upset.

Reported: 3/25/2009 at 12:30 PM STATUS: WORKING

2 Problems reported by plant 0011

Plant: 0001 Carbide Industries LLC, 4400 Bells Ln

Started: 3/13/2009 at 10:00 AM Stopped: 3/13/2009 at 10:08 AM Report ID: **07613**

Problem Description: Pollutant: PART. OPACITY Equipment: Transfer Hose

At approximately 10AM a transfer hose burst while transferring powdered lime from a tanker to our storage bin, resulting in an emission.

Reported: 3/13/2009 at 10:00 AM STATUS: WORKING

1 Problem reported by plant 0001

Plant: 0739 Dean Milk Company, 4420 Bishop Ln

Started: 3/4/2009 at 12:45 PM Stopped: 3/4/2009 at 12:45 PM Report ID: **07610**

Problem Description: Pollutant: ODOR Equipment: Scrubber

Complaint stated of objectional odor in the air.

Reported: 3/4/2009 at 12:45 AM STATUS: WORKING

Started: 3/12/2009 at 08:53 AM Stopped: 3/12/2009 at 11:00 AM Report ID: **07612**

Problem Description: Pollutant: PART. OPACITY Equipment: Scrubber

Problem with scrubber.

Reported: 3/12/2009 at 08:53 AM STATUS: WORKING

2 Problems reported by plant 0739

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 2/27/2009 at 03:30 PM Stopped: at : AM Report ID: **07606**

Problem Description: Pollutant: PART. OPACITY Equipment: Power Outage

Power Outage.

Reported: 2/27/2009 at 03:30 PM STATUS: WORKING

Started: 2/27/2009 at 09:00 PM Stopped: 2/27/2009 at 09:45 PM Report ID: **07605**

Problem Description: Pollutant: PART. OPACITY Equipment: Plant Down and Up

Plant Down and Plant back up.

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Reported: 2/27/2009 at 09:00 PM STATUS: WORKING

Started: 2/27/2009 at 04:45 PM Stopped: 2/27/2009 at 07:15 PM Report ID: 07604

Problem Description: Pollutant: PART. OPACITY Equipment: Start Up

Plant Start Up.

Reported: 2/27/2009 at 04:45 PM STATUS: WORKING

3 Problems reported by plant 0028

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 3/3/2009 at 12:23 PM Stopped: 3/3/2009 at 12:28 PM Report ID: 07608

Problem Description: Pollutant: PART. OPACITY Equipment: transfer Line

At approximately 12:23 hours, the transfer line from the 1003 Finish Mill to the 1114 Surge Bin developed a hole during the transfer causing cement dust to escape the transfer system and drift toward the south along the rail road tracks.

Reported: 3/3/2009 at 12:23 PM STATUS: WORKING

Started: 3/16/2009 at 06:12 AM Stopped: 3/16/2009 at 10:38 AM Report ID: 07614

Problem Description: Pollutant: PART. OPACITY Equipment: Preheat Tower

At approximately 7:50am, the 3rd stage on the preheat tower plugged and kiln was controlled shut down.

Reported: 3/16/2009 at 06:12 AM STATUS: WORKING

2 Problems reported by plant 0060

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Started: 3/28/2009 at 05:00 PM Stopped: 3/28/2009 at 07:00 PM Report ID: 07619

Problem Description: Pollutant: PART. OPACITY Equipment: SDRS

Excess Emissions report

Reported: 3/28/2009 at 05:00 PM STATUS: WORKING

1 Problem reported by plant 0126

Plant: 0149 Metro Sewer Dist, Morris Forman, 4522 Algonquin Pkwy

Started: 3/3/2009 at 08:00 AM Stopped: 3/4/2009 at 08:00 AM Report ID: 07609

Problem Description: Pollutant: PART. OPACITY Equipment: Digester #2

Digester #2 will be filled with digested sludge from our other three Digestors. During this fill time, it is possible for fugitive odors to escape until the digester seals.

Digester #2 has achieved and maintained seal.

Reported: 3/3/2009 at 08:00 AM STATUS: WORKING

1 Problem reported by plant 0149

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 3/2/2009 at 07:30 AM Stopped: 3/2/2009 at 10:00 AM Report ID: 07607

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

#6 Boiler Shutdown

Reported: 3/2/2009 at 07:30 AM STATUS: WORKING

1 Problem reported by plant 1333

Plant: 0189 Rohm and Haas Company, 4300 Camp Ground Rd

Started: 3/19/2009 at 09:37 AM Stopped: 3/19/2009 at 01:27 PM Report ID: **07617**

Problem Description: Pollutant: PART. OPACITY Equipment: Valve leaking

Butadiene valve failure.

Reported: 3/19/2009 at 09:37 AM

STATUS: WORKING

1 Problem reported by plant 0189
