

Louisville Metro Air Pollution Control District
Excess Emission Reports
June 2008

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 6/9/2008 at 03:10 PM Stopped: 6/10/2008 at 10:00 AM Report ID: **07475**

Problem Description: Pollutant: PART. OPACITY Equipment: disc and gearbox

Change out of the spray reactor disc and gearbox

Reported: 6/9/2008 at 03:10 PM STATUS: WORKING

Started: 6/21/2008 at 09:48 AM Stopped: 6/21/2008 at 09:54 AM Report ID: **07481**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Baghouse over loaded.

Reported: 6/21/2008 at 09:48 AM STATUS: WORKING

Started: 6/24/2008 at 01:30 AM Stopped: at : AM Report ID: **07482**

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Baghouse issues.

Reported: at : AM STATUS: WORKING

3 Problems reported by plant 0011

Plant: 0016 Anderson Wood Products, 1381 Beech St

Started: 6/10/2008 at 07:15 AM Stopped: at : AM Report ID: **07477**

Problem Description: Pollutant: PART. OPACITY Equipment: Wood Burning Boiler

Smoke problems due to the type of fuel we were burning.
Metro call report #3417273

Reported: 6/11/2008 at 08:00 AM STATUS: WORKING

Started: 6/26/2008 at 12:40 PM Stopped: 6/26/2008 at 02:10 PM Report ID: **07485**

Problem Description: Pollutant: PART. OPACITY Equipment: Dust Filter Silo

Due to mechanical failure our dust fillers on top of silo became stopped up. During the clean out sawdust became airborne. It has been repaired and is working properly now.

Reported: 6/26/2008 at 12:40 AM STATUS: WORKING

2 Problems reported by plant 0016

Plant: 0026 Blue Grass Coop., Brown-Forman, 402 MacLean Ave

Started: 6/27/2008 at 10:00 AM Stopped: at : AM Report ID: **07483**

Problem Description: Pollutant: PART. OPACITY Equipment: Wood Fired Boiler

Boiler is being shutdown for routine cleaning of the boiler wet scrubber

Reported: at : AM STATUS: WORKING

1 Problem reported by plant 0026

Plant: 0001 Carbide Industries LLC, 4400 Bells Ln

Plant: 0001 Carbide Industries LLC, 4400 Bells Ln

Started: 6/18/2008 at 07:30 AM Stopped: 6/18/2008 at 02:30 PM Report ID: 07479

Problem Description: Pollutant: PART. OPACITY Equipment: Furnace scrubber

Malfunction of furnace scrubber. Furnace has been shut off to work on the problem. Currently venting through the emergency vent stack.

Reported: 6/18/2008 at 03:00 PM STATUS: WORKING

1 Problem reported by plant 0001

Plant: 0620 John Conti Coffee, 4023 Bardstown Rd

Started: 6/16/2008 at 09:00 AM Stopped: 6/16/2008 at 09:30 AM Report ID: 07478

Problem Description: Pollutant: PART. OPACITY Equipment: After Burner

After burner would not start. The electric eye was covered by dust. This has been cleared and everything is working now.

Reported: 6/16/2008 at 09:00 AM STATUS: WORKING

1 Problem reported by plant 0620

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 6/3/2008 at 09:00 AM Stopped: 6/3/2008 at 09:25 AM Report ID: 07473

Problem Description: Pollutant: PART. OPACITY Equipment: Baghouse

Power loss to part of the plant at approximately 8:10am resulting in a sudden shut down of the kiln and 526 in line raw mill. Upon restoring power and bringing baghouses back online, fugitive dust exited out of the 526 Mill building and preheat tower at 9am and went east over the kiln toward the back of the property. CEMs and COMs are offline and will be restored ASAP.

Reported: 6/3/2008 at 09:55 AM STATUS: WORKING

Started: 6/9/2008 at 07:42 PM Stopped: 6/9/2008 at 09:30 PM Report ID: 07476

Problem Description: Pollutant: PART. OPACITY Equipment: Shutdown LG & E

LG & E cut power to Kosmos due to the demand caused from hot weather.

Reported: 6/10/2008 at 04:45 PM STATUS: WORKING

2 Problems reported by plant 0060

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Started: 6/5/2008 at 11:25 PM Stopped: 6/5/2008 at 11:40 PM Report ID: 07474

Problem Description: Pollutant: PART. OPACITY Equipment: SDRS

Incorrect calculations due to calibration failure. SDRS equipment.

Reported: 6/5/2008 at 11:25 PM STATUS: WORKING

1 Problem reported by plant 0126

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 6/19/2008 at 06:55 PM Stopped: 6/19/2008 at 07:55 PM Report ID: 07480

Problem Description: Pollutant: PART. OPACITY Equipment: TK-8K

TK-8K overfill, shutdown silo.

Reported: 6/19/2008 at 06:55 PM STATUS: WORKING

1 Problem reported by plant 1333

Plant: 0283 Zeon Chemicals L.P., 4100 Bells Ln

Started: 6/24/2008 at 08:21 AM Stopped: 6/24/2008 at 08:21 AM Report ID: **07484**

Problem Description: Pollutant: PART. OPACITY Equipment: valve left open

Caller reporting a release of 49 pounds of 1.3 butadiene due to a valve being left open.

Reported: 6/24/2008 at 08:21 AM STATUS: WORKING

1 Problem reported by plant 0283
