

Louisville Metro Air Pollution Control District
Excess Emission Event Reports
May 2009

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 5/11/2001 at 10:00 AM Stopped: at : AM Report ID: **07641**

Problem Description: Pollutant: PART. OPACITY Equipment: Scrubber

Lime issues.

Reported: 5/11/2009 at 10:20 AM STATUS: WORKING

Started: 5/11/2009 at 10:00 AM Stopped: 5/14/2009 at 12:00 AM Report ID: **07645**

Problem Description: Pollutant: PART. OPACITY Equipment: Scrubbing

Lime Issues current scrubbing 90 %.

Reported: 5/11/2009 at 10:00 AM STATUS: WORKING

2 Problems reported by plant 0011

Plant: 0299 Beechmont Press, Inc., 9951 Bunsen Way

Started: 5/1/2009 at 05:00 PM Stopped: 5/11/2009 at 10:15 AM Report ID: **07643**

Problem Description: Pollutant: PART. OPACITY Equipment: Catalytic Oxidizing

Failure of Catalytic Oxidizing Incinerator control device.

Reported: 5/1/2009 at 05:00 PM STATUS: WORKING

Started: 5/1/2009 at 08:00 PM Stopped: at : AM Report ID: **07636**

Problem Description: Pollutant: ODOR Equipment: Catalytic Oxidizing

Beechmont Press has encountered a failure at the Catalytic Oxidizing Incinerator that is used to control emissions from our 2 web presses.

Reported: 5/1/2009 at 08:00 PM STATUS: WORKING

2 Problems reported by plant 0299

Plant: 0739 Dean Milk Company, 4420 Bishop Ln

Started: 5/5/2009 at 03:30 PM Stopped: 5/5/2009 at 05:00 PM Report ID: **07638**

Problem Description: Pollutant: PART. OPACITY Equipment: Air Scrubber

Stage I pumped failed and is being replaced.

Reported: 5/5/2009 at 03:30 PM STATUS: WORKING

1 Problem reported by plant 0739

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 5/29/2009 at 02:44 AM Stopped: 5/29/2009 at 04:38 AM Report ID: **07654**

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler

LRU Boiler.

Reported: 5/29/2009 at 02:44 AM STATUS: WORKING

1 Problem reported by plant 0028

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Started: 4/28/2009 at 04:00 PM Stopped: 4/28/2009 at 04:00 PM Report ID: 07648

Problem Description: Pollutant: PART. OPACITY Equipment: joint

Report # CR4042720080800 SO2 2.8ft 2 hold expansion joint upstream.

Reported: 4/28/2009 at 04:00 PM STATUS: WORKING

Started: 5/15/2009 at 10:00 AM Stopped: 5/15/2009 at 12:25 PM Report ID: 07647

Problem Description: Pollutant: PART. OPACITY Equipment: Bad Solinod

Report # CR5051520091000 bad solinod on the gas bottle that does the daily test for SO2.

Reported: 5/15/2009 at 10:00 AM STATUS: WORKING

Started: 5/15/2009 at 06:00 PM Stopped: 5/15/2009 at 07:00 PM Report ID: 07649

Problem Description: Pollutant: PART. OPACITY Equipment: Precipitators

Report # CR 5051520091700 Unit 5 Precipitators.

Reported: 5/15/2009 at 06:00 PM STATUS: WORKING

Started: 5/15/2009 at 09:30 PM Stopped: 5/15/2009 at 09:30 PM Report ID: 07653

Problem Description: Pollutant: PART. OPACITY Equipment: Unit 5 Precipitators

Report # CR5051520091953 Unit 5 Precipitators

Reported: 5/15/2009 at 09:30 PM STATUS: WORKING

4 Problems reported by plant 0126

Plant: 0127 Lou. Gas & Elec., Mill Creek, 14660 Dixie Hwy

Started: 5/5/2009 at 11:50 AM Stopped: 5/5/2009 at 12:30 PM Report ID: 07640

Problem Description: Pollutant: PART. OPACITY Equipment: Unloading system

Report # MC0-050509-1150 A-flyash unloading system.

Reported: 5/5/2009 at 11:50 AM STATUS: WORKING

Started: 5/13/2009 at 11:00 PM Stopped: 5/14/2009 at 01:25 PM Report ID: 07646

Problem Description: Pollutant: PART. OPACITY Equipment: Particular Matter

ID # MC3051309 22:31 Particulate matter monitor.

Reported: 5/13/2009 at 11:00 AM STATUS: WORKING

2 Problems reported by plant 0127

Plant: 0149 Metro Sewer Dist, Morris Forman, 4522 Algonquin Pkwy

Started: 5/6/2009 at 08:00 AM Stopped: 5/7/2009 at 08:00 AM Report ID: 07637

Problem Description: Pollutant: PART. OPACITY Equipment: RTO #4

This is a follow up to RTO#4. Per Robin the actual completed date was 5-7-2009, 08:00am.

Reported: 5/6/2009 at 08:00 AM STATUS: WORKING

Started: 5/15/2009 at 08:00 AM Stopped: at : AM Report ID: 07644

Problem Description: Pollutant: PART. OPACITY Equipment: RTO # 2

The RTO #2 At the Morris Forman WCTP will be off line tomorrow morning for schedule maintenance.

Reported: 5/15/2009 at 08:00 AM STATUS: WORKING

Started: 5/20/2009 at 08:00 PM Stopped: at : AM Report ID: 07650

Problem Description: Pollutant: PART. OPACITY Equipment: Process Water Line

Process water line broke.

Reported: 5/20/2009 at 08:00 PM STATUS: WORKING

Plant: 0149 Metro Sewer Dist, Morris Forman, 4522 Algonquin Pkwy

3 Problems reported by plant 0149

Plant: 0189 Rohm and Haas Company, 4300 Camp Ground Rd

Started: 11/29/2007 at 10:20 PM Stopped: 11/29/2007 at 10:35 PM Report ID: 07652

Problem Description: Pollutant: HAP Equipment: Process Tank

NRC# 855891: Caller stated there was a spill of materials into containment dike due to a tank overflow. This was caused by equipment failure.

Reported: 11/30/2007 at 09:34 AM STATUS: WORKING

Started: 5/7/2009 at 04:59 PM Stopped: 5/7/2009 at 06:31 PM Report ID: 07639

Problem Description: Pollutant: PART. OPACITY Equipment: Valve flange

Valve flange in pipeline from butadiene storage tank to butadiene weigh.

Reported: 5/7/2009 at 04:59 PM STATUS: WORKING

Started: 5/28/2009 at 09:47 AM Stopped: 5/28/2009 at 10:35 AM Report ID: 07655

Problem Description: Pollutant: PART. OPACITY Equipment: Acrylic polymer powder

Buffer Pin pressure relief panel opened resulting in small amount of powder being released.

Reported: 5/28/2009 at 09:47 AM STATUS: WORKING

3 Problems reported by plant 0189

Plant: 0355 Waste Management of Kentucky, 7501 Grade Ln

Started: 5/21/2009 at 11:00 AM Stopped: 5/21/2009 at 03:00 PM Report ID: 07651

Problem Description: Pollutant: PART. OPACITY Equipment: Flare I

Flare I and complete gas system shutdown.

Reported: 5/21/2009 at 11:00 AM STATUS: WORKING

1 Problem reported by plant 0355
