

Louisville Metro Air Pollution Control District
Excess Emission Event Reports
February 2009

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 2/2/2009 at 11:24 AM Stopped: 2/2/2009 at 12:39 PM Report ID: **07581**
Problem Description: Pollutant: PART. OPACITY Equipment: Power Glitch
Toluene liquid vapor release.
Reported: 2/2/2009 at 11:24 AM STATUS: WORKING

1 Problem reported by plant 0011

Plant: 0214 Chevron USA, Bells Ln, 4401 Bells Ln

Started: 2/15/2009 at 09:00 AM Stopped: 2/15/2009 at : AM Report ID: **07597**
Problem Description: Pollutant: PART. OPACITY Equipment: terminal
Spill at bulk terminal. It did not effect any water sources.
As of 2-16-2009 04:15pm clean-up is still in progress.
Reported: 2/15/2009 at 09:00 AM STATUS: WORKING

1 Problem reported by plant 0214

Plant: 0808 DD Williamson & Company, Inc., 1901 Payne St

Started: 2/4/2009 at 02:56 AM Stopped: at : AM Report ID: **07603**
Problem Description: Pollutant: PART. OPACITY Equipment: Dryer
On the night of February 4th the D D Williamson Louisville facility located on 1901 Payne Street experienced a malfunction in the dryer unit.
Reported: 2/4/2009 at 02:56 AM STATUS: WORKING

1 Problem reported by plant 0808

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 1/21/2009 at 06:35 PM Stopped: 1/23/2009 at 11:55 PM Report ID: **07579**
Problem Description: Pollutant: PART. OPACITY Equipment: Shutdown and startup
Start up and shut down notification.
Reported: 1/21/2009 at 06:35 PM STATUS: WORKING

Started: 2/6/2009 at 02:15 PM Stopped: 2/6/2009 at 03:00 PM Report ID: **07591**
Problem Description: Pollutant: PART. OPACITY Equipment: Plant Down
Plant down @ 15:00 hrs.
Reported: 2/6/2009 at 02:15 PM STATUS: WORKING

Started: 2/6/2009 at 10:00 PM Stopped: 2/6/2009 at 11:45 PM Report ID: **07588**
Problem Description: Pollutant: PART. OPACITY Equipment: Start up
Plant start up.
Reported: 2/6/2009 at 10:00 PM STATUS: WORKING

Started: 2/6/2009 at 01:10 PM Stopped: 2/6/2009 at 01:25 PM Report ID: **07590**
Problem Description: Pollutant: PART. OPACITY Equipment: Burner #1

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Burner #1 went out.

Reported: 2/6/2009 at 01:10 PM

STATUS: WORKING

Started: 2/7/2009 at 08:45 AM Stopped: 2/7/2009 at 08:55 AM Report ID: 07586

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Malfunction unknown.

Reported: 2/7/2009 at 08:45 AM

STATUS: WORKING

Started: 2/7/2009 at 10:50 AM Stopped: 2/7/2009 at 11:05 AM Report ID: 07584

Problem Description: Pollutant: PART. OPACITY Equipment: Maintenance

Maintenance,

Reported: 2/7/2009 at 10:50 AM

STATUS: WORKING

Started: 2/7/2009 at 09:30 AM Stopped: 2/7/2009 at 10:00 AM Report ID: 07585

Problem Description: Pollutant: PART. OPACITY Equipment: Unknown

Malfunction unknown.

Reported: 2/7/2009 at 09:30 AM

STATUS: WORKING

Started: 2/9/2009 at 09:00 AM Stopped: 2/9/2009 at 09:15 AM Report ID: 07587

Problem Description: Pollutant: PART. OPACITY Equipment: Low O2

Low O2.

Reported: 2/9/2009 at 09:00 AM

STATUS: WORKING

Started: 2/10/2009 at 07:30 PM Stopped: 2/10/2009 at 10:45 PM Report ID: 07589

Problem Description: Pollutant: PART. OPACITY Equipment: Shutdown

Plant shut down.

Reported: 2/10/2009 at 07:30 PM

STATUS: WORKING

Started: 2/12/2009 at 06:15 PM Stopped: 2/12/2009 at 09:15 PM Report ID: 07594

Problem Description: Pollutant: PART. OPACITY Equipment: Plant

Plant is shut down.

Reported: 2/12/2009 at 06:15 PM

STATUS: WORKING

Started: 2/15/2009 at 03:45 PM Stopped: 2/15/2009 at 03:45 PM Report ID: 07595

Problem Description: Pollutant: PART. OPACITY Equipment: plant

Starting Plant.

Reported: 2/15/2009 at 03:45 PM

STATUS: WORKING

Started: 2/16/2009 at 08:25 AM Stopped: at : AM Report ID: 07596

Problem Description: Pollutant: PART. OPACITY Equipment: shut down

Planned shut down.

Reported: 2/16/2009 at 08:25 AM

STATUS: WORKING

Started: 2/17/2009 at 05:30 PM Stopped: 2/17/2009 at 07:00 PM Report ID: 07598

Problem Description: Pollutant: PART. OPACITY Equipment: Plant Startup

Starting Plant Up.

Reported: 2/17/2009 at 05:30 PM

STATUS: WORKING

Started: 2/17/2009 at 09:45 PM Stopped: 2/17/2009 at 10:30 PM Report ID: 07599

Problem Description: Pollutant: PART. OPACITY Equipment: Stack Gas Boiler

Stack gas Boiler went down.

Reported: 2/17/2009 at 09:45 PM

STATUS: WORKING

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 2/21/2009 at 05:15 AM Stopped: 2/21/2009 at 05:30 AM Report ID: 07600
Problem Description: Pollutant: PART. OPACITY Equipment: High O2
High O2.
Reported: 2/21/2009 at 05:15 AM STATUS: WORKING

Started: 2/24/2009 at 11:10 AM Stopped: 2/24/2009 at 11:20 AM Report ID: 07602
Problem Description: Pollutant: PART. OPACITY Equipment: Stack Gas
Stack gas failure.
Reported: 2/24/2009 at 11:10 AM STATUS: WORKING

16 Problems reported by plant 0028

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 2/11/2009 at 09:30 AM Stopped: 2/11/2009 at 09:50 AM Report ID: 07593
Problem Description: Pollutant: PART. OPACITY Equipment: Dust Collector
The draw line for the K1487 dust collector that controls the South Truck and Rail load spout backed up with cement resulting in some fugitive emissions during the loading of a truck.
Reported: 2/11/2009 at 09:30 AM STATUS: WORKING

1 Problem reported by plant 0060

Plant: 0532 Outer Loop Recycling & Disp, 2673 Outer Loop

Started: 2/20/2009 at 10:00 AM Stopped: 2/20/2009 at 04:00 PM Report ID: 07601
Problem Description: Pollutant: PART. OPACITY Equipment: flow meter pipe
Flow meter pipe/header is ready to install.
Reported: 2/20/2009 at 10:00 AM STATUS: WORKING

1 Problem reported by plant 0532

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 2/3/2009 at 01:40 PM Stopped: 2/3/2009 at 05:20 PM Report ID: 07583
Problem Description: Pollutant: PART. OPACITY Equipment: Boiler #6
Bring boiler #6 up to temperature and pressure.
Reported: 2/3/2009 at 01:40 PM STATUS: WORKING

Started: 2/3/2009 at 01:15 AM Stopped: 2/3/2009 at 05:00 AM Report ID: 07582
Problem Description: Pollutant: PART. OPACITY Equipment: Boiler
#4 Boiler emergency shut down.
Reported: 2/3/2009 at 01:15 AM STATUS: WORKING

Started: 2/5/2009 at 05:00 AM Stopped: 2/5/2009 at 07:52 AM Report ID: 07592
Problem Description: Pollutant: PART. OPACITY Equipment: #6 grate drive
#6 grate drive malfunction.
Reported: 2/5/2009 at 05:00 AM STATUS: WORKING

3 Problems reported by plant 1333

Plant: 0355 Waste Management of Kentucky, 7501 Grade Ln

Started: 1/28/2009 at 08:19 AM Stopped: 1/29/2009 at 11:45 AM Report ID: 07580

Plant: 0355 **Waste Management of Kentucky, 7501 Grade Ln**

Problem Description: **Pollutant:** PART. OPACITY **Equipment:** Power Outage

Power outage caused by weather.

Reported: 1/28/2009 **at** 08:19 AM

STATUS: WORKING

1 Problem reported by plant 0355
