

Louisville Metro Air Pollution Control District
Excess Emission Reports
August 2006

Plant: 0079 General Shale Products LLC, 212 S Park Rd

Started: 8/12/2006 at 09:00 AM Stopped: 8/28/2006 at 01:00 PM Report ID: **06969**

Problem Description: Pollutant: PART. OPACITY Equipment: A-kiln/ Scrubber

A-kiln and A-scrubber have been shut down for repairs and maintenance.

A-kiln and A-scrubber have been started back up after repairs and maintenance.

Reported: 8/14/2006 at 02:50 PM STATUS: WORKING

1 Problem reported by plant 0079

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 8/19/2006 at 03:30 PM Stopped: 8/19/2006 at 06:00 PM Report ID: **06974**

Problem Description: Pollutant: PART. OPACITY Equipment: Gas Boiler

Had a power failuter on August 19 at 11:45 pm. Power was out for 2.5 hours.

Rec'd ltr dated; 8/22/06.

Reported: 8/19/2006 at 03:37 PM STATUS: WORKING

Started: 8/28/2006 at 07:50 AM Stopped: at : AM Report ID: **06979**

Problem Description: Pollutant: PART. OPACITY Equipment: Maintenance

Maintenance scheduled shutdown.

Reported: at : AM STATUS: WORKING

2 Problems reported by plant 0028

Plant: 0148 Lou Med Center Steam Plant, 235 Abraham Flexner Way

Started: 8/15/2006 at 09:30 AM Stopped: 8/15/2006 at 01:00 PM Report ID: **06970**

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler #4

Increasing steam load on boiler to create test conditions for stack tests. Excess fuel (coal) entered furnace before actual steam load occurred. See letter to Jesse Goldsmith, dated June 23 & 14, 2006.

Rec'd voice message and fax, returned to normal @ 1:00 p.m.

Reported: 8/15/2006 at 11:40 AM STATUS: CLOSED

1 Problem reported by plant 0148

Plant: 0126 Lou. Gas & Elec., Cane Run, 5252 Cane Run Rd

Started: 8/19/2006 at 09:26 PM Stopped: 8/20/2006 at 06:14 AM Report ID: **06978**

Problem Description: Pollutant: PART. OPACITY Equipment: CR4 Precipitator

Precipitator out of service during startup.

Reported: 8/25/2006 at 03:00 PM STATUS: WORKING

1 Problem reported by plant 0126

Plant: 0127 Lou. Gas & Elec., Mill Creek, 14660 Dixie Hwy

Plant: 0127 Lou. Gas & Elec., Mill Creek, 14660 Dixie Hwy

Started: 8/10/2006 at 01:50 PM Stopped: 8/10/2006 at 01:57 PM Report ID: 06966

Problem Description: Pollutant: PART. OPACITY Equipment: BFlyash Silo

Email rec'd; 8/10/06. Loss of power control panel for the unloading system.

Rec'd email; 8/22/06: Follow up report.

Reported: at : AM STATUS: WORKING

1 Problem reported by plant 0127

Plant: 0532 Outer Loop Recycling & Disp, 2673 Outer Loop

Started: 8/20/2006 at 04:00 PM Stopped: 8/21/2006 at 09:15 AM Report ID: 06976

Problem Description: Pollutant: PART. OPACITY Equipment: Power outage

Loss of power, LG&E power outage.

Reported: at : AM STATUS: WORKING

1 Problem reported by plant 0532

Plant: 1333 Oxy Vinyls LP, 4014 Bells Lane

Started: 8/10/2006 at 07:00 AM Stopped: 8/10/2006 at 08:15 AM Report ID: 06968

Problem Description: Pollutant: PART. OPACITY Equipment: #4 Boiler Baghouse

#4 boiler baghouse damper vent closed. (Loss of air pressure)

Reported: at : AM STATUS: WORKING

Started: 8/10/2006 at 08:05 PM Stopped: 8/10/2006 at 10:10 PM Report ID: 06967

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler #4

Boiler #4.

Reported: at : AM STATUS: WORKING

Started: 8/17/2006 at 01:50 AM Stopped: 8/17/2006 at 05:30 AM Report ID: 06972

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler #6

Starting up boiler #6. There will be smoke. Will line out boiler and bring up to temperature.

Reported: 8/17/2006 at 01:45 AM STATUS: WORKING

Started: 8/19/2006 at 07:45 PM Stopped: 8/19/2006 at 07:55 PM Report ID: 06973

Problem Description: Pollutant: PART. OPACITY Equipment: Boiler #4

Boiler #4 shutdown for baghouse maintenance. Will emit smoke. Will reset baghouse comter to minimize emissions.

Reported: 8/19/2006 at 07:47 PM STATUS: WORKING

4 Problems reported by plant 1333

Plant: 0115 Swift & Company, 1200 Story Ave

Started: 8/2/2006 at 10:00 AM Stopped: at : AM Report ID: 06964

Problem Description: Pollutant: ODOR Equipment: Upper scrubber

Had to replace bleach pump.

Reported: 8/2/2006 at 11:20 AM STATUS: WORKING

Plant: 0115 Swift & Company, 1200 Story Ave

Started: 8/30/2006 at 07:35 AM Stopped: 8/30/2006 at 08:00 PM Report ID: **06977**

Problem Description: Pollutant: ODOR Equipment: Small vapor scrubber

Electrical failure on small scrubber recirculating pump.

Reported: 8/30/2006 at 07:45 AM

STATUS: WORKING

2 Problems reported by plant 0115
