

Louisville Metro Air Pollution Control District
Excess Emission Event Reports
July 2009

Plant: 0011 American Synthetic Rubber, 4500 Camp Ground Rd

Started: 7/8/2009 at 07:00 AM Stopped: 7/21/2009 at 09:00 AM Report ID: **07670**

Problem Description: Pollutant: PART. OPACITY Equipment: Gearbox

Conditions have arisen that necessitate a change out of the spray reactor disc an gear box. The spray reactor maintenance will occur on July 9th 2009.

Reported: 7/8/2009 at 07:00 AM STATUS: WORKING

1 Problem reported by plant 0011

Plant: 0438 Dawn Food Products, 6303 Kenjoy Dr

Started: 7/19/2009 at 10:09 PM Stopped: at : PM Report ID: **07672**

Problem Description: Pollutant: PART. OPACITY Equipment: Malfunction

Ammonia leak from an isolate malfunction.

Reported: 7/19/2009 at 10:09 PM STATUS: WORKING

1 Problem reported by plant 0438

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Started: 6/26/2009 at 04:00 AM Stopped: 6/26/2009 at 03:30 PM Report ID: **07668**

Problem Description: Pollutant: TAP Equipment: Silver Boiler

Down for maintenance.

Reported: 6/26/2009 at 04:00 AM STATUS: WORKING

Started: 7/2/2009 at 12:45 PM Stopped: 7/13/2009 at 07:45 PM Report ID: **07674**

Problem Description: Pollutant: PART. OPACITY Equipment: Shutdown Startup

Shutdown/Startup 7-2-2009 thru 7-13-2009

Reported: 7/2/2009 at 12:45 PM STATUS: WORKING

Started: 7/2/2009 at 12:30 AM Stopped: 7/11/2009 at 12:15 AM Report ID: **07669**

Problem Description: Pollutant: TAP Equipment: Silver Boiler

Planned shutdown.

Reported: 7/2/2009 at 12:30 AM STATUS: WORKING

Started: 7/13/2009 at 06:00 PM Stopped: 7/13/2009 at 07:45 PM Report ID: **07671**

Problem Description: Pollutant: PART. OPACITY Equipment: Startup

Notification of startup after shutdown and notificaion of high HO2.

Reported: 7/13/2009 at 06:00 PM STATUS: WORKING

Started: 7/17/2009 at 12:30 PM Stopped: 7/17/2009 at 05:30 PM Report ID: **07673**

Problem Description: Pollutant: PART. OPACITY Equipment: Outage

Outage.

Reported: 7/17/2009 at 12:30 PM STATUS: WORKING

Started: 7/24/2009 at 12:00 PM Stopped: 7/26/2009 at 02:00 PM Report ID: **07675**

Problem Description: Pollutant: PART. OPACITY Equipment: Startup Shutdown

Plant: 0028 Hexion Speciality Chemicals, 6200 Camp Ground Rd

Planned shutdown and startup

Reported: 7/24/2009 at 12:00 PM

STATUS: WORKING

Started: 7/28/2009 at 11:30 PM

Stopped: 7/29/2009 at 12:30 PM

Report ID: 07680

Problem Description:

Pollutant: PART. OPACITY

Equipment: LRU Boiler

Plant went down. 16:20 on 7-28-2009.

Reported: 7/28/2009 at 11:30 PM

STATUS: WORKING

Started: 7/28/2009 at 04:00 PM

Stopped: 7/29/2009 at 02:30 AM

Report ID: 07677

Problem Description:

Pollutant: PART. OPACITY

Equipment: Boiler

Lost boiler.

7-29-2009 Correction received to this malfunction report. Times originally indicated on this report were incorrect and updated fax was received by APCD.

Reported: 7/28/2009 at 04:00 PM

STATUS: OPEN

8 Problems reported by plant 0028

Plant: 0060 Kosmos Cement Co, 15301 Dixie Hwy

Started: 7/28/2009 at 11:45 AM

Stopped: 7/28/2009 at 12:05 PM

Report ID: 07679

Problem Description:

Pollutant: PART. OPACITY

Equipment: Fan shorted out

K546 ID Fan shorted out, resulting in loss of draft on Raw Mill Dr and it's baghouse (K545) and an uncontrolled shut down.

Reported: 7/28/2009 at 11:45 AM

STATUS: WORKING

Started: 7/28/2009 at 07:11 AM

Stopped: 7/28/2009 at 07:40 AM

Report ID: 07678

Problem Description:

Pollutant: PART. OPACITY

Equipment: Loss Power

Lost power in the 526 Mill Building.

Reported: 7/28/2009 at 07:11 AM

STATUS: WORKING

2 Problems reported by plant 0060

Plant: 0355 Waste Management of Kentucky, 7501 Grade Ln

Started: 7/27/2009 at 10:00 AM

Stopped: at : AM

Report ID: 07676

Problem Description:

Pollutant: PART. OPACITY

Equipment: condensate sump

Shutting down gas system to clean out a condensate sump on the main header.

Reported: 7/27/2009 at 10:00 AM

STATUS: WORKING

1 Problem reported by plant 0355